

SAFETY

STEEL-CRETE should not be applied where surface temperatures are below 40° F (5° C) or when there is a possibility of temperatures falling below freezing.

Cool temperatures and high humidity will retard the curing time of **STEEL-CRETE**. Take caution not to apply **STEEL-CRETE** if weather conditions do not allow for a complete cure before rain, dew or freezing temperatures.

Avoid breathing dust and getting in eyes. Where dust conditions exist that exceed nuisance dust levels set by OSHA use an approved dust mask and eye goggles.

Continuous handling of **STEEL-CRETE** may result in dry skin, use a lanolin based hand cream to restore moisture where needed. For additional safety information consult the **STEEL-CRETE** MSDS.